



服务报告 Service Report

TMPL-2021-Ver.1.0

Customer/:

Zrich shipping

Location/:

Luojing pier, Shanghai

Order No./Customer PO/:

Vessel/Site/:

M/V Talbot

Customer Requested By/:

Li Hong Gang

Equipment/Maker/Module/:

KongSberg ACC20

Page/:

Page 1 of 2

Date/:

2024-12-31

Hull No./IMO:

9453212

Main Purpose of visit :


- ME Servo motor replacement and commissioning

Customer Fault Description :

Technical Report:

Visual and inspect the servo motor, found that in the idle mode the motor is running, the internal noise is too large, especially at the encoder end. At the same time, the key pin is broken already. After confirming with C/E and 2/E on site, Our company suggestion is recommended to replace servo motor immediately. At the same time, feedback site situation to company and shipowner, later, after the shipowner agreed to replace it, the new spare parts were installed and the commissioning operation was normal.

Main engine standby, Ahead and astern start normally.



Recommendation:

Regular check of running sound and gearbox

Please rate our service :

(To be completed by the customer)

Good ☐

Acceptable ☐

Poor ☐

Comments if any

MATERIALS SUPPLIED

Qty	Item Name/Description	Item No./Part No.	Serial No.	Comments
1pcs	AC SERVO MOTOR/SGMGH-13Q5A-OM11			

Confirm the above service and materials supplied were in order

Date:
2024-12-31

Engineer signature:
Simon Shi

Work accepted on behalf of customer

Signature & ship's stamp:

